


4. Exploded View

Indoor Unit : MS05SQ NW0, MS07SQ NW0



Note) * Please ensure GCSC since the replacement parts may be changed depending upon the buyer's request.
Please check the correct parts in View RPL(Replacement Part List) on GCSC.
(GCSC Website <http://www.lge.com>)