


4. Exploded View

Indoor Unit
36k



Thermistor 1	263230C	Air	Housing color : yellow
Thermistor 2	263230A	Eva. In	Housing color : white
Thermistor 3	263230B	Eva. Out	Housing color : red

Note) * Please ensure GCSC since the replacement parts may be changed depending upon the buyer's request.
Please check the correct parts in View RPL(Replacement Part List) on GCSC.
(GCSC Website <http://biz.Lgservice.com>.)