
6. Exploded View

Model: CHBW096A1, CHBW126A1, CHBW146A1



Note) * Please ensure GCSC since the replacement parts may be changed depending upon the buyer's request. Please check the correct parts in View RPL(Replacement Part List) on GCSC. (GCSC Website http://biz.Lgservice.com,)