


7. Exploded View

UN36A (1Ø : 5, 7, 9kW)

* Condenser Assembly Repaired Parts

Description	Location No.	Quantity
Condenser Assembly,Bending	554031	1
Tube Assembly,Return Bending	352119	29
Tube Assembly,Manifold(Outdoor)	552115	1
Tube Assembly,Condenser(Out)	552113	1
Tube Assembly,Connector	352111A	1



Thermistor Assembly,NTC

Location No.	Thermistor Description	Housing Color
EBG26BK	Water In/Water Out/PHE Out	Black
EB13WHA	Pipe In	White
EBG13GR	SUCTION	Green
EBG13BK	DISCHA	Black
EBG13YL	AIR	Yellow
EBG13BR	MID-PIPE	Brown
EBG13VI	CONDENSER_PIPE	Violet
EB13WHB	VI_IN	White