
6. Exploded View



Model	Classification	Description	Part Number	Location Number	Remark
A3UW186FA5	Heating	Compressor	TBZ35295301	554160	
(MU3M19 [UE0])		Harness, Multi	EAD62228501	W6631	

NOTE

^{*} Please ensure GCSC since the replacement parts may be changed depending upon the buyer's request. Please check the correct parts in View RPL(Replacement Part List) on GCSC. (GCSC Website http://biz.Lgservice.com)